







+3,820 My






+3,820 Qz






Перемещения Z (мм). Комбинация 1 ((L1)*1+(L2)*1+(L3)*1)



■	0	0.38
■	0.38	0.77
■	0.77	1.15
■	1.15	1.53
■	1.53	1.91
■	1.91	2.3
■	2.3	2.68

■	2.68	3.06
■	3.06	3.44
■	3.44	3.83
■	3.83	4.21
■	4.21	4.59
■	4.59	4.97
■	4.97	5.36


+7,120 As нижняя по X



0	1.36
1.36	2.73
2.73	4.09
4.09	5.45
5.45	6.82
6.82	8.18
8.18	9.55

9.55	10.91
10.91	12.27
12.27	13.64
13.64	15.0
15.0	16.36
16.36	17.73
17.73	19.09


+7,120 As верхняя по X



0	0.28
0.28	0.56
0.56	0.83
0.83	1.11
1.11	1.39
1.39	1.67
1.67	1.95


1.95	2.22
2.22	2.5
2.5	2.78
2.78	3.06
3.06	3.34
3.34	3.62
3.62	3.89

+7,120 As нижняя по У






0 1.35	9.43 10.77
1.35 2.69	10.77 12.12
2.69 4.04	12.12 13.46
4.04 5.39	13.46 14.81
5.39 6.73	14.81 16.16
6.73 8.08	16.16 17.5
8.08 9.43	17.5 18.85

+7,120 As верхняя по У



+7,120 My



+7,120 Qz